

# Belgium Home Floor Renovation

**Surface Type:** Natuursteen | **Products Used:** Oxy-Klenza™ & Stain-Proof™ Original |  
**Completed:** 2015

**Accredited Applicator:** Stone Protection | **Email:** herkdestad@stoneprotection.be | **Website:**  
www.stoneprotection.be | **Phone:** +32 471 72 05 61



Before



After

## THE PROJECT:

Homeowners in Berchem, a southern district of Antwerp, were renovating their rustic home when they came across a natural stone floor that had been hidden under carpet for years. They decided to remove the carpeting and restore and protect the stone floor.

## SPECIAL REQUIREMENTS:

Cleaner:

- Removal of existing stains
- Safe to use on natural stone
- Heavy duty to remove general grime and stains caused by oil/grease, food, and beverages





Sealer:

- Impregnating sealer to protect deep into the stone's pores
- Invisible and breathable
- Create and maintain a surface that is easier to clean

### THE DRY-TREAT SOLUTION:

Miranda and her team at Stone Protection cleaned the floor with Oxy-Klenza and sealed it with Stain-Proof. Due to the heavy amount of residue on the stone, they applied the Oxy-Klenza and allowed it to sit for about 30 minutes. The stains were then removed with the help of a floor scrubber.

After the stone was clean, they applied Stain-Proof to protect the newly remerged stone floor from stains as well as make it easier to clean. Miranda suggested to the homeowners that they use Rejuvenata Active for their regular cleaning.

